



1580 TUBE MOTOR

DRIVE END MOTOR MOUNT



DRIVE END BRACKET



DO NOT WIRE IN PARALLEL

IDLER END BRACKET

